
Ceres Gym Project

Floor Renovation Update: March 8, 2011



Before Construction



Damage found on subfloor



Demolition of old floor



Joists during construction



Construction of new subfloor



Subfloor completed



Underlayment for new floor